

Technical drawing of a rectangular transformer. The drawing shows the transformer from an isometric perspective. Dimensions are indicated by red arrows and labels: L1 (width of the base), L2 (width of the top), L3 (width of the base), L4 (width of the top), W1 (width of the base), W2 (width of the top), H1 (height of the base), and H2 (height of the top).